OEM DISCUSSION | ADVANCING TECHNOLOGY INSPIRING AND PREPARING THE TECHNICIANS OF TOMORROW

Mobilize Summit 2023

AGENDA

- Introduction
- The Future of Vehicle Innovation
- ADAS Calibrations & Scanning
- Resources
- Careers & Training
- Summary



INTRODUCTION



DAVID SOSA

Manager, Rivian Automotive
Collision Research &
Development Workshop




JOEY GRAMMATICO Manager, I-CAR Product


The Future of Vehicle Innovation Is Here


- RIVIAN -




Material Matrix- R1 Tophat (Body)














Material Matrix- R1 Closures













Material Matrix-R1 Skateboard (Frame)














Material Matrix- EDV Tophat (Body)












Material Matrix- EDV Closures














Material Matrix- EDV Skateboard (Frame)











Material Repairability Guide



OalasKasa	MatarialTona	Welding		Hart Charlet anima	Cold	
Color Key	Material Type	MAG	STRSW	Heat Straightening	Straightening	
	Conventional Steel	Yes	Yes	60 sec. @ 600° C	Yes	
	Advanced High Strength Steel	Yes	Yes	No	Yes	
	Ultra High Strength Steel	No	Yes	No	Yes	
	Press- Hardened Steel	No	Yes	No	No	
	Aluminum Sheet	Yes	No	60° C	Yes	
	Aluminum Extrusion	No	No	No	No	
	Magnesium	No	No	No	No	
	Plastic	N/A	N/A	N/A	N/A	



High Voltage Battery Pack- Inspection and Support

RCI-30-23-001-1: High Voltage (HV) Battery Storage and Handling Guidelines

Rivian Automotive, LLC - Service Guideline &

Document Type	Collision Repair Information Document
Date	February 6, 2023
Affected Region(s)	USA
Affected Model(s)	All Models
Model Year(s)	2022+
Vehicle System	30 - High Voltage Battery

This procedure requires RiDE. Review the RiDE instructions specific to this procedure before starting work.

Some RiDE routines are restricted and will need to be performed by a Rivian service center.

- Always refer to the Rivian service manual for up-to-date information regarding the disablement of the High Voltage (HV) system and safety precautions/steps to follow prior to performing any work on the HV system.
- Rivian recommends that only Factory Certified Service Technicians inspect and repair the HV System in Rivian vehicles. Please contact your regional Rivian Collision/Service Team to request more information or for assistance with repairs

General Information 🥜

To promote and maintain its rigorous standards of quality and safety. Rivian Automotive provides the collision industry with important information, and safety precautions, to use when storing and handling HV battery packs.

To lower the risk of possible electrocution, always assume the HV battery pack, and associated components, are energized and fully charged until their status can be verified by following the HV disabling guidelines in the service manual.

/ Warning:

Exposed HV electrical components, cables, and batteries present potential HV shock hazards that could result in bodily injury or death.

Any venting/off-gassing HV battery vapors may be toxic and/or flammable and could result in bodily injury or death

Physical damage to the HV battery may result in a fire or in immediate, or delayed, release of toxic and/or flammable gases which could result in bodily injury or death.








A HV battery, pack as well as all related HV components, pose a significant electrocution risk if the enclosure or the built-in safety components have experienced significant damage during a collision event. Rivian strongly recommends that you contact your regions Rivian Collision/Service team for assistance with repairs.

If possible, prior to allowing the vehicle to enter the shop area, perform the steps in the table below to ensure the vehicle is safe to work on. Make emergency response access, if needed.




No.	Inspection Point	Inspect For	Action
1	Battery Enclosure	Sparks, smoke or flames	Call Emergency Services
		Electrical odors and fumes	
		Gurgling or bubbling noises	
2		Any external leak(s) of battery cooling fluid (check coolant level)	Contact your regional Rivian Collision/Service Team to
		Signs of moisture accumulation and possible corrosion	request more information or assistance with repair.
		Any deformations, cracks, dents, or tears that compromise the battery internals	
		Damaged HV Connectors	
		Damaged Enclosure Seals	
		Evidence of electrical arc event resulting in welding or spatter marks	

Evidence of electrical arc event resulting in welding or spatter marks	






Repair Procedure Research- Unique Repair Sectioning




1. Investigate Alternate Repair Options



4. Design Final Procedure



2. Design the Repair



5. Physical Validation




RIVIAN

Let's Talk ADAS Calibrations and Scanning

Advanced driver-assistance systems (ADAS)

ADAS features in the vehicle are primarily focused on collision avoidance technologies (for example, lane departure warning and blind-spot applications) and driver aids, such as night vision, driver alertness and adaptive cruise control



Scanning and Calibration



Ultrasonic Sensors (12) Cameras (3) Radars (5) Modules (4)

- Long Range Camera
- Driver Assistance Camera
- Stereo Vision Camera
- Lane Change Camera
- Front Radars
- Corner Radar
- Ultrasonic Sensors

RCI-86-22-001-3: Driver+ Calibration Requirements and Best Practices. R1T and R1S

Rivian Automotive, LLC Position Statement

Document Type	Collision Repair Information Document
Date	February 3, 2023
Affected Region(s)	USA
Affected Model(s)	R1T, R1S
Model Year(s)	2022-Present
Vehicle System	86 - Driver Assistance

Rivian has established important guidelines regarding collision repair and interaction with parts on Rivian vehicles to help ensure the vehicle is repaired to Rivian standards. Certified Collision Centers and the collision industry must follow these guidelines to uphold Rivian's standards of safety and quality.

Repair guidelines, position statements, and repair procedures published by Rivian are engineered and teated to help ensure Rivian vehicles are repaired to provide quality, performance, safety, and dusability. To meet Mina Repair standards, repairs should be performed by Rivian Certified Technicians using Rivian approved repair procedures took, and Rivian Original Equipment Pair.

Driver+ Overview

Driver is Rivian's suite of Advanced Driver-Assistance Systems (ADAS). The system is comprised of cameras, radar senors, antennas, and utbrasonic sensors that aid with vehicle operation, To meet Kivan Standards, repairs involving Driver-components should be performed by a Rivian Certified Technician at either a Rivian Service Center or Rivian Certified Collision Center. After repair, the Driver-system will need to be calibrated before the vehicle can be returned to the customer. Refer to the appropriate service procedure(s) for detailed and whicle-specific calibration instructions.

Always refer to the appropriate Rivian Service Manual for information on removal, installation, fault tracing, and calibration.

RCI-86-22-002-1: Driver+ Calibration Requirements and Best Practices, EDV

Rivian Automotive, LLC Position Statement

Document Type	Collision Repair Information Document
Date	February 3, 2023
Affected Region(s)	USA
Affected Model(s)	EDV
Model Year(s)	2022-Present
Vehicle System	86 - Driver Assistance

Rivian has established important guidelines regarding collision repair and interaction with parts on Rivian vehicles to help ensure the vehicle is repaired to Rivian standards. Certified Collision Centers and the collision industry must follow these quidelines to updold Rivian's standards of safety and quality.

Repair guidelines, position statements, and repair procedures published by Rivian are engineered and tested to help ensure Rivian vehicles are repaired to provide quality, performance, safety, and durability. To meet Rivian Repair standards, repairs should be performed by Rivian Certified Technicians using Rivian approved repair procedures, tools, and Rivian Original Equipment Parts.

Driver+ Overview

Driver is Rivian's suite of Advanced Driver-Assistance Systems (ADAS). The EDV uses cameras, radar sensors, antennas, and ultrasonic sensors to aide with driver assistance, parking, obstacle maneuvering, and delivery navigation. Proper cleaning and maintenance of the components are critical to whicle operation and driver safety. The components are located on the vehicle in areas that may sustain damage. If any Driver+ component needs to be replaced due to damage, only new, Kiwian components should be used to make sure Driver+ + functions and operations meet Rivian standards. Failure to replace a damaged component with a new, Rivian Driver+Component may result in the Driver+ system ont working as sintender (nisking the safety of the



Training & Resources

Driving the Future for Women in Collision Repair



WIN Wear Contact Us Sign In Join WIN Q

About -

Membership +

Sponsorship -

Industry & Events -

Programs -

Technical Courses

The Importance of Weld Testing



The Evolution of ADAS



Understanding Dynamic Calibrations



Understanding Static Calibrations



Let's Talk Resources for Researching Repair Procedures

The Why's

Fascia Repair Guidelines

RIVIAN

RCI-52-23-001-1: Fascia, Front, Upper Repair

Rivian Automotive, LLC Position Statement

Document Type	Collision Repair Information Document
Date	May 17, 2023
Affected Region(s)	All
Affected Model(s)	R1T, R1S
Model Year(s)	2022+
Vehicle System	52 - Body

Rivian has established important guidelines regarding collision repair and interaction with parts on Rivian vehicles to help ensure the vehicle is repaired to Rivian standards. Certified Collision Centers and the collision ndustry must follow these guidelines to uphold Rivian's standards of safety and quality.

lepair guidelines, position statements, and repair procedures published by Rivian are engineered and tested to nelp ensure Rivian vehicles are repaired to provide quality, performance, safety, and durability. To meet Rivian Repair standards, repairs should be performed by Rivian Certified Technicians using Rivian approved repair ocedures, tools, and Rivian Original Equipment Parts.

Fascia, Front, Upper Repair Guidelines

Rivian passenger vehicles are equipped with radar sensors located behind the front bumper fascia. To avoid interference with the Sensor, Radar, Front, Center and the integrated safety systems, repair is not allowed to the

In addition to repairs, repainting (primers, sealers, and base coats) is not allowed in the No-Repair Zone. Only clearcoat can be applied in the No-Repair Zone. If any repair beyond clearcoat application is required in the radar transmission area, the bumper must be replaced. Repairs outside the No-Repair Zone area are allowed To locate the Sensor, Radar, Front, Center under the Fascia, Front, Upper, measure up from the Camera, Bumper, ront. Then, measure left and right to create a rectangle; the rectangle represents the radar transmission area and No-Repair Zone.

Figure 1, No-Repair Zone



XPEL Paint Protection Film •ULTIMATE PLUS™ Gloss Finish STEALTH™ Satin Finish

Clearcoat Blending

RCI-52-22-001-2: Clearcoat Blending

Rivian Automotive, LLC Position Statement

Document Type	Collision Repair Information Document
Date	July 27, 2023
Affected Region(s)	USA
Affected Model(s)	R1T, R1S
Model Year(s)	2022+
Vehicle System	52 - Body

Rivian has established important guidelines regarding collision repair and interaction with parts on Rivian vehicles to help ensure the vehicle is repaired to Rivian standards. Certified Collision Centers and the collision industry must follow these guidelines to uphold Rivian's standards of safety and quality.

Repair guidelines, position statements, and repair procedures published by Rivian are engineered and tested to help ensure Rivian vehicles are repaired to provide quality, performance, safety, and durability. To meet Rivian Repair standards, repairs should be performed by Rivian Certified Technicians using Rivian approved repair procedures, tools, and Rivian Original Equipment Parts.



Warning: The use of clearcoat blending procedures may void the paint manufacturer's warranties.

Rivian does not recommend the use of any clearcoat blending procedures in warranty or collision refinishing

Technicians should not perform clearcoat blending due to the following:

- Clearcoat blending does not allow material to properly adhere to the refinished surface.
- Clearcoat blending does not provide sufficient ultraviolet (UV) protection to the refinished area.
- · Clearcoat blending can degrade the durability of the material, exposing it to the elements. This can result in discoloration, delamination, hazing, fading, peeling, and a noticeable blend edge

Rivian advises technicians to perform the following clearcoat procedures:

- . To restore the factory finish, the final clear coat should be applied to the panel's edge or natural
- · It may be necessary to remove exterior trim, moldings, weather stripping, handles, emblems, decals, or glass for clearcoat application. The removal of certain components can cause fault codes and may require recalibration or reinitialization to ensure all systems are functioning properly.

Rivian's position applies to all approved paint systems. Please refer to the paint manufacturer's guidelines for additional information on recommended processes and warranty restrictions.

Always refer to the appropriate Rivian Repair procedure for the most up to date information regarding specifications as well as location, position, operation sensitivity, part numbers and any revisions listed.

Fastener Re-use



RCI-52-22-006-2: Threaded Fastener Re-use (Threadlocker)

Rivian Automotive, LLC Position Statement and Technical Notes

Document Type	Collision Repair Information Document
Date	5/24/2022
Affected Region(s)	USA
Affected Model(s)	R1T, R1S, EDV
Model Year(s)	2022 +
Vehicle System	52 - Body

Factory Material	Purpose	Location	Visual Identifier (Color)	Approved Service Alternative
ND Microspheres Blue	Medium Strength Thread Locker	Fastener Threads (General assembly and mild stressed fasteners	Blue low viscosity liquid or anaerobic gel	Loctite 243/290 Permatex 24835 Vibra-Tite VT121/VT125
ND Patch Yellow	Thread sealant and thread locker	Wheel liners and under shields	Yellow viscosity liquid or anaerobic gel	Re-usable 3X. If in doubt replace with NEW fastener with
				factory applied Yellow Patch
ND Epoxy- Lock ND TA 800 Orange or Red	High Strength Thread Locker	Fastener Threads (structural, heavy mechanical	Red low viscosity liquid or anaerobic gel	Loctite 263/277 Permatex 26210
		assembly, high stressed fasteners)		Vibra-Tite 140/135
ND ST-3 White	Thread Sealant	Fastener Threads (connection points with liquids present)	White paste	Loctite 5452 Permatex 57535 Vibra-Tite VT420
ND Plastisol Black	Fastener Seal	Fastener mating flange surface (Areas that require moisture protection)	Black sealant	Loctite SI 593 Permatex 80060 Vibra-Tite VT998

Fastener re-use is not possible if:

- The fasteners are torque-to-vield
- Note: Some bolts may have the same visual appearance, but the function and placement may
- The fasteners are prevailing torque types.
 The fasteners have plastic that is deformed during installation.




- . The fastener Nuts have Teflon lining.
- The fastener has any damage.
 The parent fastener material has any damage.

If accessible, use chemical cleaner to ensure the area is clean and ready for application. Be sure to remove all

Always refer to the appropriate Rivian Repair procedure for the most up to date information regarding


Service Documentation



RIVIAN R1T Service Manual > Introduction > 10 - Steering > 14 - Brakes > 18 - Suspension > 22 - Wheels and Tires > 26 - Thermal Management > 30 - HV Battery > 34 - High Voltage Distribution > 38 - Front Drive Unit > 42 - Rear Drive Unit > 46 - Frame > 52 - Body > 56 - Closures > 60 - Exterior Attachments > 64 - Interior > 68 - Seats > 72 - Occupant Protection > 78 - Low Voltage Electrical > 82 - Lighting > 86 - Driver Assistance > 96 - Supplemental Components > 98 - Maintenance and Inspection

Position Statements & Guidelines

https://www.oem1stop.com/content/rivian



Technical Support

I-CAR Repairability Technical Support (RTS)





	Coli	sion Br	aking		
Pre-Co	lision S	ystem			•
Camer	as/Sens	ors:			
	Nor F		Hieror		
	00.8950	ed Econ	t Burns	22	











Adaptin	rd Front	Lights	ng Siyat	cm-
Camer	so/Sero	ors:		
Sense	Sinds		N Local	
		_		

DTCvSet	X	
Syracin ML	2,	



UTES Set	X	-	imoissoon
System MEL			- 8

eneras/Sensors:			
reportió Bythis Identi	of Hose)	lumper (over
200000	SSS 100		9
TCs Set			o de

2021 Toyota Camry Hybrid



Click the links below for directions; definitions; articles; and additional RTS portal information such as OEM position statements and publications.

How To Use The OEM Calibration

Requirements Search

Vehicle System Definitions

ADAS, Calibration, And Scanning Article

Hotspot

Additional RTS OEM Information



Camera Near Rearview Mirror

OEM Name: Forward Recognition Camera

Calibration/Initialization Requirement Events:

- · If camera is removed/installed or replaced
- If DTC indicates
- · If windshield is removed/installed or replaced

Camera Near Rearview Mirror	Yes	Not Identified
DTC Set	Х	
Scan Tool Required	Χ	
Special Tools Required	Х	

Systems Affected:

Adaptive Cruise Control

Collision Braking

Lane Departure Warning

Lane Keep Assist Adaptive Lighting 1



Technical Support





Position Statements

Statement on Repair Procedures

What is OEM1Stop?

OEM1Stop is intended to provide vehicle repair technicians with easy access to the most up-to-date repair information made available by each of its participating automakers.

There is no registration required for OEM1Stop itself, however, on each participating automaker's page you'll find buttons directing you to that manufacturer's repair information websites. Each of those sites is operated independently by the respective automaker, and each requires its own registration/login process. These sites may also require the purchase of daily/weekly/monthly/annual subscriptions to access repair information.

Recently Added

Ford - On Target 2023 Vol. 3 Added

Tesla Service Repair Information Added

Ford - On Target 2023 Vol. 2 Added

Rivian - Updated Clearcoat Blending Position Added

Rivian - Updated EDV Material Matrix Added

Rivian - Position Statements Added





















































































ADDITIONAL SOURCES TO ACCESS REPAIR INFORMATION

OEM Websites

AllData

I-CAR

Sun Systems

OEC RepairLogic

CCC Repair Methods

"BUSINESS OPPORTUNITIES ARE LIKE BUSES. THERE'S ALWAYS ANOTHER ONE COMING"


Richard Branson

Let's Talk Careers and Training

TECHFORCE STUDY

While **232,000** techs were needed in 2021 across automotive, diesel, and collision repair, schools were graduating only **42,000**.

In collision alone, the demand was **35,000** techs while only **4,500** graduated.



"We as an industry are finding that we are facing greater and greater difficulty in attracting and recruiting and retaining that human capital that we need to perform these safe and proper repairs"

-Aaron Schulenburg, SCRS executive director.

Technical Support

Industry Feedback

ACADEMY



- · Curriculum can be lengthy and it's difficult to stay engaged and motivated
- · Curriculum is outdated and not tailored for entry-level learners
- Completing a school program but not having the skills needed to begin working in a shop



- · Difficulty attracting students to the program
- · Program completion rates are not as expected
- · Non-flexible educational programs that do not easily integrate with curriculum
- Current I-CAR Curriculum
 - · Difficult to align curriculum with skill exercises
 - Curriculum modules assume a level of knowledge that some students don't yet have
 - · Curriculum modules are lengthy and it's difficult to keep students engaged or sense of accomplishment
- · Cost of required tools, equipment, and materials
- · Current curriculum does not prepare students for shops
- · Minimal interactions with local shops about recruiting talent



Shop

- Current school curriculums do not provide students the skills they need to begin working in a shop
- · Finding and retaining entry-level technicians
- · Spending excessive funds recruiting and retaining talent
- Minimal interactions with local schools to recruit talent

Technical Support

I-CAR Academy

ACADEMY

- Entry-level technician core learning areas based on industry feedback to better prepare students for the industry
- Curriculum separated by core learning areas which result in Badges
- Industry-recognized certification provided upon completion of Badges
- Aligns knowledge learning with skills learning
- Educator and student materials to support live and online teaching and learning
- Credits earned in school translate into the professional environment



Training

Required Training: 27 Courses

Instructor Led Training (ILT)

- Collision: Welcome to The Rivian Adventure Collision Onboarding
- Collision: RLN Office Hours
- Collision: Rivian Collision Training R1T/R1S Roadshow
- Collision: High Voltage Level 2 Mechanical Training R1T/R1S and EDV
- Collision: ADAS Recalibration Training R1T/R1S/EDV



Online Training (OLT)

- EHS: High Voltage Level 1
- Collision/Service: Rivian EHS High Voltage Glove Protocol
- Collision/Service: Pathways for Collision Repairs
- Collision/Service: Rivian R1T/R1S Functions & Driver Training Overview
- Collision/Service: Rivian R1T/R1S ADAS Sensor & Camera Placement
- Collision/Service: Rivian R1T/R1S Display & Reset
- Collision/Service: Redline EV NanoLeak Locator
- Collision/Service: Rivian R1T Body Panel Adjustment Tips
- Collision: Vehicle Repair guidelines Vehicle Protection Practices
- Collision: Vehicle Repair Guidelines Separating Factory Connections
- Collision: Vehicle Repair Guidelines Separating Mechanically Fastened Connections
- Collision/Service: R1T/R1S Glass, Roof (Removed and Replace)
- Collision/Service: R1T/R1S Front Roof Applique (Remove and Replace)
- Collision/Service: ADAS Recalibration Job Aid R1T/R1S
- Collision/Service: Rivian EDV Windshield Replacement
- Collision/Service: EDV 12V Battery Removal/Installation



SUMMARY

With proper resources and mentorship, today's students can navigate a career path that reinforces their passions and enables them to create the positive change the industry needs. Emerging technology enables students to carve out a niche specialty, and fosters compensation that makes them feel secure in their career goals.

THANK YOU

Liz Stein

Liz.stein@oeconnection.com

www.oeconnection.com

EXTRA SLIDES TO 'PLUG-AND-PLAY'

HOW WE GET THERE

TECHNOLOGY

Envision possible career paths

Engage worldwide methodologies with web-enabled technologies

RESOURCES

Engage top-line web services with cutting-edge deliverables

INSPIRE

Maximize timely deliverables for real-time schemas

PLAN TO EDUCATE AND INSPIRE

EXPLORE	RESEARCH	EDUCATE	ENCOURAGE	REPEAT
Insert	Insert	Insert	Insert	Insert

AREAS OF FOCUS

Understand Training, Resources, and Financial support Available to Students

Develop winning strategies to keep ahead of the competition

Capitalize on low-hanging fruit to identify a ballpark value

Visualize customer directed convergence

Become a Mentor that Inspires and Enables Career Goals to Become a Reality

Iterative approaches to corporate strategy

Establish a management framework from the inside